
Preliminary Hand-Held Air Monitoring Locations | ITC Deer Park Tank Fire

Reading Date 3/27/2019 3:00:00 AM to 3/27/2019 5:00:00 AM



Recent Benzene Detections

Location Category	Reading Date	Concentration
Division B	3/27/2019 03:30:41	0.200 ppm
	3/27/2019 04:06:10	0.310 ppm
	3/27/2019 04:33:34	0.350 ppm
Division E	3/27/2019 03:04:16	2.400 ppm
	3/27/2019 04:04:56	1.100 ppm
	3/27/2019 03:33:23	2.000 ppm
	3/27/2019 04:08:37	0.425 ppm
	3/27/2019 03:17:03	1.275 ppm
	3/27/2019 03:37:04	0.525 ppm
	3/27/2019 04:12:56	0.350 ppm
	3/27/2019 03:21:14	0.875 ppm
	3/27/2019 04:00:10	0.540 ppm
	3/27/2019 04:46:15	0.625 ppm
	3/27/2019 04:40:48	0.825 ppm
	3/27/2019 04:47:08	1.080 ppm
	3/27/2019 04:56:12	1.200 ppm
	3/27/2019 04:52:47	1.325 ppm
Impacted Tank Farm	3/27/2019 04:03:38	0.360 ppm
	3/27/2019 04:22:07	2.850 ppm
Industrial Area	3/27/2019 03:00:25	1.250 ppm
	3/27/2019 03:25:23	0.180 ppm
	3/27/2019 03:18:13	1.975 ppm

Not all real time data on this website have undergone full QA/QC (quality assurance/quality control) analysis. It has been provided expeditiously to regulatory agencies and on-site contractors for informational purposes only